

Applications

Make	Model	Type
Audi	A1	
Skoda	Octavia	
	Yeti	
Volkswagen	Beetle	1.4 direct injection 4 cylinder TSI and TSi Blue Motion engines (turbo and supercharged)
	Eos	
	Golf	
	Jetta	
	Passat	
	Polo	
	Scirocco	
	Tiguan	
Touran		

Our products are designed to be used correctly and with care for the purpose for which they are intended. No liability is accepted by Sonic for incorrect use of any of our products, and Sonic cannot be held responsible for any damage to personnel, property or equipment when using the tools. Incorrect use will also invalidate the warranty.

If applicable, the applications database and any instructional information provided has been designed to offer general guidance for a particular tool's use and while all attention is given to the accuracy of the data no project should be attempted without referring first to the manufacturer's technical documentation (workshop or instruction manual) or the use of a recognised authority such as Autodata.

It is our policy to continually improve our products and thus we reserve the right to alter specifications and components without prior notice. It is the responsibility of the user to ensure the suitability of the tools and information prior to their use.

SONIC
equipment

Instructions

Auxilliary Drive Belt Wrench Petrol TFSi 16mm VAG - 1.4




829092 - Auxilliary Drive Belt Wrench

Description:
A 16.0 mm across flats spanner with PVC handle intended for use on VAG vehicles (predominantly Volkswagen) utilising the 1.4 TSI engines. The cranked spanner is required for releasing tension on the auxiliary drive belt, which is achieved by rotating the engines' spring loaded belt Tensioner away from the belt.

Equivalent to OEM T10447



Components

Ref	Comp	OEM	Description
1		T10447	Tensioner Spanner



Instructions

The following instructions are for guidance only. Please refer to OEM derived data such as the vehicles manufactures own data or Autodata. The use of these engine timing tools is purely down to the user's discretion and Sonic cannot be held responsible for any damage caused what so ever.



*Pin no included